




EXCEPTIONAL[®]
Metals



NOTE:
ACTUAL LOCATION OF THE SIDE LAP VAPOR SEALANT
(INTERIOR JOINT OR EXTERIOR JOINT) MUST BE
DETERMINED BY THE MECHANICAL ENGINEER AND OR
ARCHITECT OF RECORD

REVISED:	07/24/2018	INSULATED METAL WALL PANELS
AUTHOR	BVANOCHT	EM 7.2 INSUL-RIB™ PANEL
SCALE:	NONE	JOINT DETAIL